

23rd May 2011

**RECALL ALERT for INSPECTION of ALL
Petzl SCORPIO via ferrata lanyards**



PETZL has advised that a SCORPIO L60 lanyard was involved in a via ferrata accident in Grenoble, France.

The probability of this defect recurring is very low but if you are in the UK or Ireland you are asked to **immediately stop using the Scorpio lanyard** and to send it for inspection to Lyon Equipment Ltd. Full details are available by clicking [here](#), by following links at www.lyon-outdoo.co.uk or by emailing scorpio@lyon.co.uk

Further details can be found on Petzl's website [here](#) or by going to www.petzl.com and following the "latest news" links.

Please accept our apologies for this inconvenience. We will resolve this as quickly and efficiently as possible.

A handwritten signature in black ink, appearing to read 'Jon. Capper'.

Jonathan Capper, Managing Director
For and on behalf of Lyon Equipment Ltd